

13611700588

AK18327 (RP)


FGPSF 1.5

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

004785932FLE

Contract# 7619

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number AKN001002925	2. Page 1 of 3	3. Emergency Response Phone 1-800-424-9300	4. Manifest Tracking Number 004785932 FLE		
5. Generator's Name and Mailing Address UIS EPA REGION 10 (B. PERKINS) 1200 6TH AVENUE, SUITE 900 SEATTLE, WA 98101 Generator's Phone: (206) 553-6396			Generator's Site Address (if different than mailing address) US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501				
6. Transporter 1 Company Name EMERALD ALASKA, INC			U.S. EPA ID Number AKR000004184				
7. Transporter 2 Company Name WEAVER BROTHERS			U.S. EPA ID Number AKD002848372				
8. Designated Facility Name and Site Address US ECOLOGY IDAHO, INC. 20400 LEMLEY RD GRAND VIEW, ID 83624 Facility's Phone: (800) 274-1516			U.S. EPA ID Number IDD073114654				
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	X	1. RQ, UN3082, WASTE ENVIRONMENTALLY HAZARDOUS SUBSTANCES, LIQUID, N.O.S. (TETRACHLOROETHENE), 9, PGIII, RQ=F002, ERG#171	5	DM	2200	P	F002
	X	2. RQ, UN3077, WASTE ENVIRONMENTALLY HAZARDOUS SUBSTANCES, SOLID, N.O.S. (TETRACHLOROETHYLENE), 9, PGIII, RQ=F002, ERG#171	1	DM	600	P	F002
		3. ERG#171					
		4.					
14. Special Handling Instructions and Additional Information 1)USE25178 F002 PURGE WATER 2)26607 F002 SOIL							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Officer's Printed/Typed Name Brandon Perkins			Signature <i>Brandon Perkins</i>			Month Day Year 11 26 12	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:				
	Transporter signature (for exports only):						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name John E. Perez		Signature <i>John E. Perez</i>			Month Day Year 12 5 12	
TRANSPORTER	Transporter 2 Printed/Typed Name Eric WBI 237		Signature <i>Eric WBI 237</i>			Month Day Year 12 14 12	
	18. Discrepancy						
DESIGNATED FACILITY	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	18b. Alternate Facility (or Generator)		USEPA SF  1397835			Manifest Reference Number: U.S. EPA ID Number	
	Facility's Phone:						
	18c. Signature of Alternate Facility (or Generator)					Month Day Year	
DESIGNATED FACILITY	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
	1. H132	2. H132	3.	4.			
DESIGNATED FACILITY	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
	Printed/Typed Name Conan Koshner			Signature <i>Conan Koshner</i>			Month Day Year 11 18 13

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number AKN001002925	2. Page 1 of 3	3. Emergency Response Phone 1-800-424-9300	4. Manifest Tracking Number 004785932 FLE		
5. Generator's Name and Mailing Address UIS EPA REGION 10 (B. PERKINS) 1200 6TH AVENUE, SUITE 900 SEATTLE, WA 98101 Generator's Phone: (206) 553-6396				Generator's Site Address (if different than mailing address) US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501			
6. Transporter 1 Company Name EMERALD ALASKA, INC				U.S. EPA ID Number AKR000004184			
7. Transporter 2 Company Name WEAVER BROTHERS				U.S. EPA ID Number AKD002848372			
8. Designated Facility Name and Site Address US ECOLOGY IDAHO, INC. 20400 LEMLEY RD GRAND VIEW, ID 83624 Facility's Phone: (800) 274-1516				U.S. EPA ID Number IDD073114654			
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	X	1. RQ, UN3082, WASTE ENVIRONMENTALLY HAZARDOUS SUBSTANCES, LIQUID, N.O.S. (TETRACHLOROETHENE), 9, PGIII, RO=F002, ERG#171	5	DM	2200	P	F002
	X	2. RQ, UN3077, WASTE ENVIRONMENTALLY HAZARDOUS SUBSTANCES, SOLID, N.O.S. (TETRACHLOROETHYLENE), 9, PGIII, RO=F002, ERG#171	1	DM	600	P	F002
		3. ERG#171					
14. Special Handling Instructions and Additional Information 1) USE25178 F002 PURGE WATER 2) 26607 F002 SOIL							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Brandon Perkins				Signature <i>Brandon Perkins</i>		Month Day Year 11 20 12	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:				
	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name John E. Perez		Signature <i>John Perez</i>		Month Day Year 12 5 12		
	Transporter 2 Printed/Typed Name Eric WBI 237		Signature <i>Eric WBI 237</i>		Month Day Year 12 14 12		
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	18b. Alternate Facility (or Generator)				Manifest Reference Number: U.S. EPA ID Number		
	Facility's Phone:						
	18c. Signature of Alternate Facility (or Generator)				Month Day Year		
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H132		2. H132		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Corian Kestner				Signature <i>Corian Kestner</i>		Month Day Year 11 18 13	

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number AKN001002925	2. Page 1 of 3	3. Emergency Response Phone 1-800-424-9300	4. Manifest Tracking Number 004785932 FLE	
5. Generator's Name and Mailing Address UIS EPA REGION 10 (B. PERKINS) 1200 6TH AVENUE, SUITE 900 SEATTLE, WA 98101 Generator's Phone: (206) 553-6396			Generator's Site Address (if different than mailing address) US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501			
6. Transporter 1 Company Name EMERALD ALASKA, INC			U.S. EPA ID Number AKR000004184			
7. Transporter 2 Company Name WEAVER BROTHERS			U.S. EPA ID Number AKD002848372			
8. Designated Facility Name and Site Address US ECOLOGY IDAHO, INC. 20400 LEMLEY RD GRAND VIEW, ID 83624 Facility's Phone: (800) 274-1516			U.S. EPA ID Number IDD073114654			
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
1.	RQ, UN3082, WASTE ENVIRONMENTALLY HAZARDOUS X SUBSTANCES, LIQUID, N.O.S. (TETRACHLOROETHENE), 9, PGIII, RO=F002, FRG#171	5	DM	2200	P	F002
2.	RQ, UN3077, WASTE ENVIRONMENTALLY HAZARDOUS X SUBSTANCES, SOLID, N.O.S. (TETRACHLOROETHYLENE), 9, PGIII, RO=F002, ERG#171	1	DM	600	P	F002
3.						
4.						
14. Special Handling Instructions and Additional Information 1)USE25178 F002 PURGE WATER 2)26607 F002 SOIL						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name Brandon Perkins		Signature <i>Brandon Perkins</i>		Month Day Year 11 20 12		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name John E. Perez		Signature <i>John E. Perez</i>		Month Day Year 12 5 12		
Transporter 2 Printed/Typed Name Eric WBI 237		Signature <i>Eric WBI 237</i>		Month Day Year 12 14 12		
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: _____						
18b. Alternate Facility (or Generator) U.S. EPA ID Number _____						
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator) Month Day Year _____						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H132		2. H132		3. _____		4. _____
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Coran Koster		Signature <i>Coran Koster</i>		Month Day Year 11 18 13		

DESIGNATED FACILITY

U.S. EPA Form 8700-22

Read all instructions before completing this form.

1. This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
2. Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators, 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

I. Instructions for Generators

Item 1. Generator's U.S. EPA Identification Number

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

Item 2. Page 1 of ____

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any).

Item 3. Emergency Response Phone Number

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

1. Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
2. Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
3. Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

Note: Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

Item 4. Manifest Tracking Number

This unique tracking number must be pre-printed on the manifest by the forms printer.

Item 5. Generator's Mailing Address, Phone Number and Site Address

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

Item 6. Transporter 1 Company Name, and U.S. EPA ID Number

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

Item 7. Transporter 2 Company Name and U.S. EPA ID Number

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)

Item 9a. If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this Item next to the corresponding hazardous material identified in Item 9b.

Item 9b. Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number (UN/NA) and Packing Group for each waste as identified in 49 CFR 172. Include technical name(s) and reportable quantity references, if applicable.

Note: If additional space is needed for waste descriptions, enter these additional descriptions in Item 27 on the Continuation Sheet (EPA Form 8700-22A). Also, if more than one Emergency Response phone number applies to the various wastes described in either Item 9b or Item 27, enter applicable Emergency Response phone numbers immediately following the shipping descriptions for those Items.

Item 10. Containers (Number and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

TABLE I.--TYPES OF CONTAINERS

BA = Burlap, cloth, paper, or plastic bags.	DT = Dump truck.
CF = Fiber or plastic boxes, cartons, cases.	DW = Wooden drums, barrels, kegs.
CM = Metal boxes, cartons, cases (including roll-offs).	HG = Hopper or gondola cars.
CW = Wooden boxes, cartons, cases.	TC = Tank cars.
CY = Cylinders.	TP = Portable tanks.
DF = Fiberboard or plastic drums, barrels, kegs.	TT = Cargo tanks (tank trucks).
DM = Metal drums, barrels, kegs.	

Item 11. Total Quantity

Enter, in designated boxes, the total quantity of waste. Round partial units to the nearest whole unit, and *do not* enter decimals or fractions. To the extent practical, report quantities using appropriate units of measure that will allow you to report quantities with precision. Waste quantities entered should be based on actual measurements or reasonably accurate estimates of actual quantities shipped. Container capacities are not acceptable as estimates.

Item 12. Units of Measure (Weight/Volume)

Enter, in designated boxes, the appropriate abbreviation from Table II (below) for the unit of measure.

TABLE II.--UNITS OF MEASURE

G = Gallons (liquids only).	N = Cubic Meters.
K = Kilograms.	P = Pounds.
L = Liters (liquids only).	T = Tons (2000 Pounds).
M = Metric Tons (1000 kilograms).	Y = Cubic Yards.

Note: Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

Item 13. Waste Codes

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

Item 14. Special Handling Instructions and Additional Information

1. Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
2. This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

Item 15. Generator's/Officer's Certifications

1. The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
2. Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/offeror certification, to indicate that the individual signs as the employee or agent of the named principal.

Note: All of the above information except the handwritten signature required in Item 15 may be pre-printed.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKN001002925	22. Page 2 / 3	23. Manifest Tracking Number 004785932FLE			
24. Generator's Name (206) 553-6396		US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501					
25. Transporter <u>3</u> Company Name TOTEM OCEAN TRAILER EXPRESS		U.S. EPA ID Number WAD070397955					
26. Transporter <u>4</u> Company Name EMERALD SERVICES, INC.		U.S. EPA ID Number WAD058364647					
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information							
TRANSPORTER	33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
	34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
DESIGNATED FACILITY	35. Discrepancy						
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKN001002925	22. Page 2 / 3	23. Manifest Tracking Number 004785932FLE			
24. Generator's Name (206) 553-6396		US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501					
25. Transporter <u>3</u> Company Name TOTEM OCEAN TRAILER EXPRESS		U.S. EPA ID Number WAD070397955					
26. Transporter <u>4</u> Company Name EMERALD SERVICES, INC.		U.S. EPA ID Number WAD058364647					
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
			No.	Type			
32. Special Handling Instructions and Additional Information							
TRANSPORTER	33. Transporter Acknowledgment of Receipt of Materials		Signature		Month	Day	Year
	Printed/Typed Name						
DESIGNATED FACILITY	34. Transporter Acknowledgment of Receipt of Materials		Signature		Month	Day	Year
	Printed/Typed Name						
35. Discrepancy							
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number		22. Page	23. Manifest Tracking Number			
		AKN001002925		2 / 3	004785932FLE			
24. Generator's Name		US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501 (206) 553-6396						
25. Transporter <u>3</u> Company Name		TOTEM OCEAN TRAILER EXPRESS			U.S. EPA ID Number WAD070397955			
26. Transporter <u>4</u> Company Name		EMERALD SERVICES, INC.			U.S. EPA ID Number WAD058364647			
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
				No.	Type			
32. Special Handling Instructions and Additional Information								
TRANSPORTER	33. Transporter <u>2</u> Acknowledgment of Receipt of Materials		Signature		Month Day Year			
	Printed/Typed Name				12/14/12			
	34. Transporter <u>4</u> Acknowledgment of Receipt of Materials		Signature		Month Day Year			
DESIGNATED FACILITY	Printed/Typed Name				11/1/13			
	35. Discrepancy							
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKN001002925		22. Page 2 / 3	23. Manifest Tracking Number 004785932FLE		
		24. Generator's Name US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501 (206) 553-6386					
25. Transporter _____ Company Name TOTEM OCEAN TRAILER EXPRESS		U.S. EPA ID Number WAD070397455					
26. Transporter _____ Company Name EMERALD SERVICES, INC.		U.S. EPA ID Number WAD050382117					
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information							
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name _____		Signature _____		Month _____	Day _____	Year _____
	34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name _____		Signature _____		Month _____	Day _____	Year _____
DESIGNATED FACILITY	35. Discrepancy _____						
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

Instructions—Continuation Sheet
U.S. EPA Form 8700-22A

Read all instructions before completing this form. This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used—press down hard.

This form must be used as a continuation sheet to U.S. EPA Form 8700-22 if:

- More than two transporters are to be used to transport the waste; or
- More space is required for the U.S. DOT descriptions and related information in Item 9 of U.S. EPA Form 8700-22.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, or disposal facilities to use the uniform hazardous waste manifest (EPA Form 8700-22) and, if necessary, this continuation sheet (EPA Form 8700-22A) for both interstate and intrastate transportation.

I. Instructions for Generators

Item 21. Generator's ID Number

Enter the generator's U.S. EPA twelve digit identification number or, the State generator identification number if the generator site does not have an EPA identification number.

Item 22. Page _____

Enter the page number of this Continuation Sheet.

Item 23. Manifest Tracking Number

Enter the Manifest Tracking number from Item 4 of the Manifest form to which this continuation sheet is attached.

Item 24. Generator's Name—

Enter the generator's name as it appears in Item 5 on the first page of the Manifest.

Item 25. Transporter—Company Name

If additional transporters are used to transport the waste described on this manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 3 Company Name. Also enter the U.S. EPA twelve digit identification number of the transporter described in Item 25.

Item 26. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 4 Company Name. Each Continuation Sheet can record the names of two additional transporters. Also enter the U.S. EPA twelve digit identification number of the transporter named in Item 26.

Item 27. U.S. D.O.T. Description Including Proper Shipping Name, Hazardous Class, and ID Number (UN/NA)

For each row enter a sequential number under Item 27b that corresponds to the order of waste codes from one continuation sheet to the next, to reflect the total number of wastes being shipped. Refer to instructions for Item 9 of the manifest for the information to be entered.

Item 28. Containers (No. And Type)

Refer to the instructions for Item 10 of the manifest for information to be entered.

Item 29. Total Quantity

Refer to the instructions for Item 11 of the manifest form.

Item 30. Units of Measure (Weight/Volume)

Refer to the instructions for Item 12 of the manifest form.

Item 31. Waste Codes

Refer to the instructions for Item 13 of the manifest form.

Item 32. Special Handling Instructions and Additional Information

Refer to the instructions for Item 14 of the manifest form.

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number	AKN001002925	22. Page	3 / 3	23. Manifest Tracking Number	004785932FLE						
24. Generator's Name		(206) 553-6396						US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501					
25. Transporter 5 Company Name		STEVE FORLER TRUCKING						U.S. EPA ID Number WAR000001263					
26. Transporter 6 Company Name								U.S. EPA ID Number					
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes			
	No.	Type											
32. Special Handling Instructions and Additional Information													
5													
TRANSPORTER	33. Transporter 5 Acknowledgment of Receipt of Materials		Signature		Month Day Year								
	Printed/Typed Name Michael Suhle		[Signature]		11/15/13								
DESIGNATED FACILITY	34. Transporter Acknowledgment of Receipt of Materials		Signature		Month Day Year								
	Printed/Typed Name												
35. Discrepancy													
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)													

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKN001002925		22. Page 3 / 3	23. Manifest Tracking Number 004785932FLE		
24. Generator's Name (206) 553-6396		US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501					
25. Transporter <u>5</u> Company Name STEVE FORLER TRUCKING		U.S. EPA ID Number WAR000001263					
26. Transporter <u>6</u> Company Name		U.S. EPA ID Number					
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
			No.	Type			
32. Special Handling Instructions and Additional Information 5							
TRANSPORTER	33. Transporter <u>5</u> Acknowledgment of Receipt of Materials		Signature		Month Day Year		
	Printed/Typed Name Michael Suhle		Michael Suhle		1 / 15 / 13		
DESIGNATED FACILITY	34. Transporter Acknowledgment of Receipt of Materials		Signature		Month Day Year		
	Printed/Typed Name Steve Forler		Steve Forler		1 / 15 / 13		
35. Discrepancy							
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKN001002925	22. Page 3 / 3	23. Manifest Tracking Number 004785932FLE			
24. Generator's Name (206) 553-6396		US EPA REGION 10 4TH & GAMBELL PARKING LOT ANCHORAGE, AK 99501					
25. Transporter <u>5</u> Company Name STEVE FORLER TRUCKING		U.S. EPA ID Number WAR000001263					
26. Transporter <u>6</u> Company Name		U.S. EPA ID Number					
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information 5							
TRANSPORTER	33. Transporter <u>5</u> Acknowledgment of Receipt of Materials Printed/Typed Name Michael Surka		Signature Michael Surka		Month 1	Day 15	Year 13
	34. Transporter <u>6</u> Acknowledgment of Receipt of Materials Printed/Typed Name		Signature		Month	Day	Year
DESIGNATED FACILITY	35. Discrepancy						
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number <div style="text-align: center;">AKN001002925</div>		22. Page <div style="text-align: center;">373</div>	23. Manifest Tracking Number <div style="text-align: center;">004785932FLE</div>		
24. Generator's Name <div style="text-align: center;">US EPA REGION 10 4TH & GAMBELL PARKING LOT (206) 553-6396 ANCHORAGE, AK 99501</div>					U.S. EPA ID Number		
25. Transporter <u>5</u> Company Name <div style="text-align: center;">STEVE FORLER TRUCKING</div>					U.S. EPA ID Number <div style="text-align: center;">WAR000001263</div>		
26. Transporter <u>6</u> Company Name					U.S. EPA ID Number		
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
			No.	Type			
32. Special Handling Instructions and Additional Information							
TRANSPORTER	33. Transporter <u>5</u> Acknowledgment of Receipt of Materials		Signature		Month	Day	Year
	Printed/Typed Name <i>Michael Seckle</i>		<i>Michael Seckle</i>		1	15	12
DESIGNATED FACILITY	34. Transporter <u>6</u> Acknowledgment of Receipt of Materials		Signature		Month	Day	Year
	Printed/Typed Name						
35. Discrepancy							
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

RECEIVED

JAN 31 2013

Instructions—Continuation Sheet
U.S. EPA Form 8700-22A

Read all instructions before completing this form. This form has been designed for use on a 12-pitch (elite) typewriter; a firm print can also be used—press down hard.

OFFICE OF
ENVIRONMENTAL CLEANUP

This form must be used as a continuation sheet to U.S. EPA Form 8700-22 if:

- More than two transporters are to be used to transport the waste; or
- More space is required for the U.S. DOT descriptions and related information in Item 9 of U.S. EPA Form 8700-22.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, or disposal facilities to use the uniform hazardous waste manifest (EPA Form 8700-22) and, if necessary, this continuation sheet (EPA Form 8700-22A) for both interstate and intrastate transportation.

I. Instructions for Generators

Item 21. Generator's ID Number

Enter the generator's U.S. EPA twelve digit identification number or, the State generator identification number if the generator site does not have an EPA identification number.

Item 22. Page

Enter the page number of this Continuation Sheet.

Item 23. Manifest Tracking Number

Enter the Manifest Tracking number from Item 4 of the Manifest form to which this continuation sheet is attached.

Item 24. Generator's Name—

Enter the generator's name as it appears in Item 5 on the first page of the Manifest.

Item 25. Transporter—Company Name

If additional transporters are used to transport the waste described on this manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 3 Company Name. Also enter the U.S. EPA twelve digit identification number of the transporter described in Item 25.

Item 26. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 4 Company Name. Each Continuation Sheet can record the names of two additional transporters. Also enter the U.S. EPA twelve digit identification number of the transporter named in Item 26.

Item 27. U.S. D.O.T. Description Including Proper Shipping Name, Hazardous Class, and ID Number (UN/NA)

For each row enter a sequential number under Item 27b that corresponds to the order of waste codes from one continuation sheet to the next, to reflect the total number of wastes being shipped. Refer to instructions for Item 9 of the manifest for the information to be entered.

Item 28. Containers (No. And Type)

Refer to the instructions for Item 10 of the manifest for information to be entered.

Item 29. Total Quantity

Refer to the instructions for Item 11 of the manifest form.

Item 30. Units of Measure (Weight/Volume)

Refer to the instructions for Item 12 of the manifest form.

Item 31. Waste Codes

Refer to the instructions for Item 13 of the manifest form.

Item 32. Special Handling Instructions and Additional Information

Refer to the instructions for Item 14 of the manifest form.